

SERVICE BULLETIN

AUGUST 1995

MFG: MANCO PRODUCTS, INC.
NAME: SEE DARTRON

GO-KART FRAME UPDATE

AFFECTED MODELS

Go-Karts equipped with enlarged hole for brake line.

MFG: MANCO PRODUCTS
NAME: GO-KARTS
Type: Non-Kiddie

SYMPTOM

Excessive stress causing frame rail to crack.

CORRECTIVE ACTION

Install frame brace.

Frame, Brace Left Part#008111

Updated parts will be sent at no charge.

10/1/96 NOTE: Crack must be welded up.

Call (800) 854-3140 or (503) 363-7533 if you have any questions.

JJ Amusements, Inc.
A Corporation of Oregon

2315 Pringle Road SE
Salem, Oregon 97302
(800) 854-3140
FAX (503) 363-7885

RECEIVED

OCT 01 1996

BUREAU OF
FAIR RIDES INSPECTION

Inside: Go-Kart Muffler Service Bulletin..

News from CPSC 1045

U.S. Consumer Product Safety Commission

Office of Information and Public Affairs

Washington, D.C. 20207

For Immediate Release
July 16, 1996
Release # 96-167

Contact: Kate Premo
(301) 504-0580 Ext. 1187

CPSC, Manco Products Announce Recall to Repair Go-Kart Axles

WASHINGTON, D.C.- In cooperation with the U.S. Consumer Product Safety Commission (CPSC), Manco Products Inc., of Fort Wayne, Ind., is recalling for repair approximately 300,000 go-karts with exposed rear axles. Riders can be seriously injured or killed if their long, loose hair or clothing becomes entangled on the rotating axle.

One child died and two others were seriously injured when their hair or clothing became entangled on the rotating rear axles of Manco go-karts. The children ranged in age from eight to 11 years old.

The one- and two-seat go-karts are powered by gasoline engines. Some models have brush bars to protect riders from low tree branches and other foliage. Each go-kart has a black serial number on a white label located on the floor pan immediately in front of the driver's seat.

All Manco go-karts with an exposed "live" rear axle are involved in this recall. To determine whether their go-kart is involved in this recall, consumers should stand behind the kart, with the engine off, and push the go-kart by hand. If the axle connecting the two rear wheels rotates, the go-kart is subject to this recall.

Outdoor power equipment stores, specialty stores, department stores, and hardware stores sold Manco labeled go-karts nationwide from January 1972 through June 1996 for about \$600 to \$2,000. Sears, Roebuck & Co. sold the go-karts under the Sears name from 1977 to 1983. Western Auto has sold the go-karts under the "Phoenix" label since 1987. Manco has sold the karts under the "Fox" label since 1990.

Consumers should stop using the recalled go-karts immediately and contact Manco at (800) 293-0795. Consumers should provide the model number and serial number of the kart when calling. Manco will send consumers a free axle guard kit with instructions for easy installation. Consumers can also contact the Manco dealer from which their go-kart was purchased for free installation of the axle guard kit.

The U.S. Consumer Product Safety Commission protects the public from unreasonable risks of injury or death from consumer products under the agency's jurisdiction. To report a dangerous product or a product-related injury and for information on CPSC's fax-on-demand service, call CPSC's hotline at (800) 638-2772 or CPSC's teletypewriter at (800) 638-8270. To order a press release through fax-on-demand, call (301) 504-0051 from the handset of your fax machine and enter the release number. Consumers can obtain this recall information at CPSC's web site at <http://www.cpsc.gov> or via Internet gopher services at cpsc.gov. Consumers can report product hazards to info@cpsc.gov.

###

RECEIVED

BUREAU OF
FAIR RIDES INSPECTION