

Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Unit: Winston-Salem Compliance West Field Office	Location of Inspection: Winston-Salem Pinnacle Building
Inspection Team: James Dempsey	Date of Inspection: 10/08/2021
1.	Unit Manager: Ben Harris
2.	Additional Comments:
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapters used or two prong extension cords
itional Comments, notations, and abatement information (i	including date): All ok : 10/08/2021

Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Ten fire extinguishers inspected (SA-772292, YP-234285, YE-208191, SL 102203, ZD-926241, X-530590, MR-669188, MR-669014, AB-847629, MR-669961) All ok-10/08/2021

Additional Comments, notations, and abatement information (including date): Defibrillation electrode pads (Phillips Adult / Child Multifunction Electrode Pads (2) Part # M3713A expires 2022-05-31, Defib battery went bad-need to repl. spare. Philips Med. Sys. M3863A LiMnO2 DC 12v, 4.2 Ah. During recent power outage, it was noted that the emergency lighting in both stairwells had no power-hazardous to employees-during next power outage, CSHO will verify if this still an issue.

NCDOL S

Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (amanda.carroll@labor.nc.gov) to be uploaded to the intranet and the specific Unit.

Unit: District 1	Location of Inspection: Asheville Office
Inspection Team:	Date of Inspection: October 29, 2021
1. Kristie Hall	Unit Manager: Kay Knezevich
2	Additional Comments:
Ζ.	No Issues.
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapters used or two prong extension cord
itional Comments, notations, and abatement information (i	including date):

Fi	re Hazards and Egress: Check appropriate box when con-	dition is identified and make notation
	Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
	Emergency Exit lighting is NOT working correctly	Exit doors in working condition
	Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
	Flammable/Combustibles stored correctly	Chemicals stored correctly
	Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Kiddie Fire Extinguishers (#RD-379022 and #RD-379023)

Additional Comments, notations, and abatement information (including date): The AED (HeartStart FR2+ defibrillator) was checked, to include: located in designated location, no damage or missing parts, battery was charged, a spare battery was present, and AED pads are current.

Employee Safety and Health Program



Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (amanda.carroll@labor.nc.gov) to be uploaded to the intranet and the specific Unit.

Unit: Compliance - West	Location of Inspection: Charlotte
Inspection Team:	Date of Inspection: October 29, 2021
1. Griselle Negron	Unit Manager: Paul Sullivan
	Additional Comments:
2.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
dissing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
itional Comments, notations, and abatement information (including date):

ems stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #)

Additional Comments, notations, and abatement information (including date): 10/27/2021 - AED battery was replaced. Admi will order a new battery to maintain it as a spare.

NCDOL S

Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Unit: OSH Compliance East	Location of Inspection: Lake Boone Trail – 1 st , 2 nd , 3 rd Floors; Parking Decks
Inspection Team:	Date of Inspection: October 29, 2021
1. Deborah Samad	Unit Manager: TBA (Nicole Brown)
	Additional Comments:
Z.	Light fixtures in both stairwells have been replaced. Inspection
3.	Team has requested test instructions since no instructions are visible on the fixtures.

Inspection Information

Damaged cords (any type) Missing ground pin on electrical cord		Exposed energized parts
Missing ground pin on electrical cord		, , ,
	X	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:		Outlet missing cover or broken cover
		Two prong adapter used or two prong extension cord

Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Inspected 10/29: KL-719206; BA-820835; RX-347124. Noted inspected landlord's agent on 9/20/21: SL-128343; SX-011828; BX-7495
itional Comments, notations, and abatement information (inclu	iding date):