

# **Employee Safety and Health Program**

### **Unit and Field Office Inspection Form**

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Unit: Winston-Salem Compliance West Field Office	Location of Inspection: Winston-Salem Pinnacle Building
Inspection Team: James Dempsey	Date of Inspection: 9/10/2021
1.	Unit Manager: Ben Harris
2.	Additional Comments:
3.	

Electrical Cords and Outlets: Check appropriate bo	x when condition is identified and add notation
Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapters used or two prong extension cords
Additional Comments, notations, and abatement informa	tion (including date): All ok : 9/10/2021

Exit doors in working condition
Block Exit doors
Chemicals stored correctly
Fire extinguishers inspected (identify by Serial #) Ten fire   extinguishers inspected (SA-772292, YP-234285, YE-208191, SL   102203, ZD-926241, X-530590, MR-669188, MR-669014, AB-   847629, MR-669961) All ok-9/10/2021
L



## **Employee Safety and Health Program**

#### Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>amanda.carroll@labor.nc.gov</u>) to be uploaded to the intranet and the specific Unit.

Unit: District 1	Location of Inspection: Asheville Office
Inspection Team:	Date of Inspection: September 24, 2021
1. Kristie Hall	Unit Manager: Kay Knezevich
2	Additional Comments:
2.	No Issues.
3.	

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapters used or two prong extension cord
ditional Comments, notations, and abatement information (i	ncluding date):

	Blocked fire extinguishers
Emergency Exit lighting is NOT working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Kiddie Fire Extinguishers (#RD-379022 and #RD-379023)



Г

## **Employee Safety and Health Program**

#### Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Unit: Compliance – West Bureau	Location of Inspection: Charlotte Field Office
Inspection Team:	Date of Inspection: 9/14/2021
1. Ted Hendrix	Unit Manager: Paul Sullivan
	Additional Comments:
2.	
3.	

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
litional Comments, notations, and abatement information (i	including date): No issues noted.



## **Employee Safety and Health Program**

#### Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Unit: OSH Compliance East	Location of Inspection: Lake Boone Trail – $1^{st}$ , $2^{nd}$ , $3^{rd}$ Floors; Parking Decks
Inspection Team:	Date of Inspection: September 30, 2021
1. Deborah Samad	Unit Manager: TBA (Nicole Brown)
	Additional Comments:
2.	Light fixtures in West Stairwell still awaiting repair.
3.	

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
litional Comments, notations, and abatement information (in	ncluding date):

	Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
X	Emergency Exit lighting is working correctly	Exit doors in working condition
	Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
	Flammable/Combustibles stored correctly	Chemicals stored correctly
	Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) 9/30/21: noted all inspected by landlord's agent on 9/20/21: KL-719206; BA-820835; BX-749520; RX-347124; SX-011828; SL-128343.