

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Dawain Faison (dawain faison@labor.ne.gov). to be uploaded to the intranet and the specific Unit.

Unit: Budget	Location of Inspection: Budget, Labor 31dq. 30
Inspection Team:	Date of Inspection:
1. Angela Hamilton	Unit Manager: Jack Brinson
2.	Additional Comments:
3	
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
Two prong adapter used or two prong extension cord	Appliances plugged into a power strip (Refrigerator, microwave toaster, space heater, etc.)

Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (Identify by Serial #) NO. PE-800380 inspected and 5K868



Great Job

Employee Safety and Health Program

Unit and Field Office Inspection Form

8

工

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Dawain Faison (dawain.faison@labor.nc.gov). to be uploaded to the intranet and the specific Unit.

Unit: Research & Policy w It Grap	Location of Inspection: Labor Bldg. 4+n Floor
Inspection Team:	Date of Inspection: 7/6/16
1. Javanah Weecken	Unit Manager: Gary Franks
2. Kathul Canadu	Additional Comments:
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
Two prong adapter used or two prong extension cord	Appliances plugged into a power strip (Refrigerator, microwave toaster, space heater, etc.)

ems stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
mergency Exit lighting is working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #)

Additional Comments, notations, and abatement information (including date):

Name: Unit Inspection form Decement Owner:

Thank you!"



Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Dawain Faison (dawain.faison@labor.nc.gov). to be uploaded to the intranet and the specific Unit.

Unit: Administration	Location of Inspection: OSH Review Commission
Inspection Team:	Date of Inspection: 7/7/16
1. Crystal Moss	Unit Manager: Karissa Sluss
2. Todd McNoldy	Additional Comments:
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
Two prong adapter used or two prong extension cord	Appliances plugged into a power strip (Refrigerator, microwave toaster, space heater, etc.)

Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #)5KL7P (inspected 6/16), 5KL7R (inspected 6/16), and 5KL7Q (inspected 6/16). Per Ms. Sluss, all extinguishers have been inspected in the last two weeks but have not had the dates updated on the extinguisher itself.



Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Dawain Faison (dawain.faison@labor.nc.gov). to be uploaded to the intranet and the specific Unit.

Unit: Commissioners Ofc/ Legal Affairs	Location of Inspection: Labor Building - Commismer office / (e.gg/
Inspection Team:	Date of Inspection: 6/16/16
1. Chanel Brown	Unit Manager: Dolores Q & Jane Gilchrist Additional Comments:
2. Mildred Rivera	Additional comments.
3.	

Inspection Information

Cords in walkways		Extension cords used as permanent wiring
Damaged cords (any type)		Exposed energized parts
Missing ground pin on electrical cord		Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:		Outlet missing cover or broken cover
Two prong adapter used or two prong extension cord	0	Appliances plugged into a power strip (Refrigerator, microwave toaster, space heater, etc.)

Additional Comments, notations, and abatement information (including date):

- Room 243 2nd Floor Microwave and Refrigerator plugged into a power strip
- Room 248 2nd Floor Coffee maker plugged into a power strip

Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers:
dditional Comments, notations, and abatement information (inclu	ding date):
	· · · · · · · · · · · · · · · · · · ·



Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Dawain Falson (dawain.falson@laber.ne.gov). to be uploaded to the intranet and the specific Unit.

Unit: Human Resurces	Location of Inspection: Human Resurces Suite
Inspection Team:	Date of Inspection: 7/6/16
1. Saran Beth Kunce	Unit Manager: Penasue Cottem
2 Cana Rusie	Additional Comments:
3.	

Inspection Information

Damaged cords (any type)	
Dairiaged Coros (any type)	Exposed energized parts
Missing ground pin on electrical cord	Dalsy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
Two prong adapter used or two prong extension cord	Appliances plugged into a power strip (Refrigerator, microwave toaster, space heater, etc.)
itional Comments, notations, and abatement information (includi	ng date):

Items stored within 3 feet of a heater and/or heat source		Blocked fire extinguishers
Emergency But lighting is working correctly	1.	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)		Block Exit doors
Flammable/Combustibles stored correctly		Chemicals stored correctly
Excessively warm/overheated cords or equipment:		Fire extinguishers inspected (identify by Serial #)



Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Dawain Faison (dawain faison@labor.ne.gov). to be uploaded to the Intranet and the specific Unit.

Unit: Communications	Location of Inspection: Communications, 1st fl
Inspection Team:	Date of Inspection:
1. Angela Hamilton 2.	Unit Manager: Dolores Quesen berry Additional Comments:
3.	

Inspection Information

Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
wo prong adapter used or two prong extension cord	Appliances plugged into a power strip (Refrigerator, microwave toaster, space heater, etc.)

Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) NO. and sign

Additional Comments, notations, and abatement information (including date):