NCDOL S

Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (Amanda.Carroll@labor.nc.gov). To be uploaded to the intranet and the specific Unit.

Unit: OSH Compliance East	Location of Inspection: Lake Boone Tr., 1 st , 2 nd , 3 rd Floors and Parking Deck
Inspection Team:	Date of Inspection: 9/28/2017
1. Deborah Samad	Unit Manager: Bruce Miles
2	Additional Comments:
2.	
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
itional Comments, notations, and abatement information (including date):

Fire Hazards and Egress: Check appropriate box when condition is identified and make notation			
	Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers	
X	Emergency Exit lighting is working correctly See below:	Exit doors in working condition	
	Space heaters meet testing laboratories criteria (Identify)	Block Exit doors	
	Flammable/Combustibles stored correctly	Chemicals stored correctly	
	Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) KL-719206; MX-832020; YZ-947616; YZ- 947814; ZC-871744; YZ-947825	

Additional Comments, notations, and abatement information (including date): Emergency lighting/Exit signs which FALL: 3rd Fl.: Lab. door to main office, #61; at door to Info. Proc. Asst.'s office, #52. 2nd Fl.: Conf. Rm B, #45; Training room (rear), #47. West stairwell: On landing between parking deck and 1st fl., #95: (test button jammed, unable to test); at door to 2nd Fl., #92; on landing between 2nd and 3rd fl., #91. East stairwell: Landing between 3rd and 2nd floor, #100; at door to 2nd Fl., #101; on landing between 1st and 2nd floor, #102: (test button jammed, unable to test).



Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (amanda.carroll@labor.nc.gov) to be uploaded to the intranet and the specific Unit.

Unit: WBT GUPLY - CHAPLOTTE I	_ocation	of Inspection: (The Delice
Inspection Team:	Date of	Inspection: 25-7/59/9
THE WALL	Jnit Mar	nadar: David
		al Comments:
2.		
Inspect	ion Ir	nformation
Electrical Cords and Outlets: Check appropriate box wh	nen cor	ndition is identified and add notation
		Extension cords used as permanent wiring
Damaged cords (any type)	5(1) K	Exposed energized parts
Missing ground pin on electrical cord	16	Daisy chain (power strip plugged into another power strip)
	457	Outlet missing cover or broken cover
Excessively warm/overheated cords or equipment:	N	
<u> </u>	<u> 125</u>	Two prong adapter used or two prong extension cord
Additional Comments, notations, and abatement information (includin	g date):
* KEMBAD GOTH MEMS		
* REMOJED BOTH MENS		
Willes .		
Fire Hazards and Egress: Check appropriate box when	conditi	on is identified and make notation
Items stored within 3 feet of a heater and/or heat source	N	Blocked fire extinguishers
Emergency Exit lighting is working correctly	Ч	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	N	Block Exit doors
Flammable/Combustibles stored correctly	4	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	19	Fire extinguishers inspected (identify by Serial #)
ماما		ANNUAL EXTRIGUISHER MINT. DUE
		THE PROPERTY OF
Additional Comments, notations, and abatement information (i	ncluding	q date);

NCDOL S

Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (amanda.carroll@labor.nc.gov) to be uploaded to the intranet and the specific Unit.

Unit: District 1	Location of Inspection: Asheville Office
Inspection Team:	Date of Inspection: September 29, 2017
1. Kristie Hall	Unit Manager: Kay Knezevich
2. Leighton Dowdle	Additional Comments:
	No hazards were found during the inspection.
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring		
Damaged cords (any type)	Exposed energized parts		
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)		
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover		
	Two prong adapter used or two prong extension cord		
Additional Comments, notations, and abatement information (including date):			

tems stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
mergency Exit lighting is working correctly	Exit doors in working condition
pace heaters meet testing laboratories criteria (Identify)	Block Exit doors
lammable/Combustibles stored correctly	Chemicals stored correctly
xcessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Kiddie Fire Extinguishers (#RD-379022 and #RD-379023)
nal Comments, notations, and abatement information (inclu	L Luding date):

MONTHLY OFFICE INSPECTION WINSTON-SALEM FIELD OFFICE

DATE OF	INSPECTION: 9/29/17	PERFORM	IED BY: Sam & Russ
FIRE EXT	INGUISHERS:	*	
	Front Lobby (#1)		
	Hallway (#2)		
	South Stairwell (#3)	3	
_/	Sign Out board (#4)		FIRST AID KIT
	IH Lab (#5)		OK OK
1	South Exit Stairwell (#6)		X Needs supplies
1	Main Fire Stairwell (#6)		(Bandages - Strong - Strups)
EMERGEN	NCY LIGHTS		DEFILBRILLATOR
1	South Exit Stairwell (#27)		Electrode Pads
1	South Hallway (#29)		Battery OK
1	North Walkway (#31)		
	Supervisor's Hall (#33)		
EXIT SIGN	S		BATHROOMS
1	Front Door		Men's
V.	Front Stairwell (#48)		Women's
	South Work Station (#30)		
1	Back Door (#28)		
	North Work Station (#32)		
	South Reception (#34)		
	Top of Main Stairs (#51)		
V	In Front of Elevator (#50)		