

### **Unit and Field Office Inspection Form**

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Unit: Wilming Tom	Location of Inspection: Wilming Ton
Inspection Team:	Date of Inspection: $\frac{y}{23}/20ZI$
1. Atamaninek	Unit Manager:
2	Additional Comments:
£.	-
3.	

## **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
lissing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
tional Comments, notations, and abatement information (in	ncluding date):

ms stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
nergency Exit lighting is working correctly	Exit doors in working condition
pace heaters meet testing laboratories criteria (Identify)	Block Exit doors
ammable/Combustibles stored correctly	Chemicals stored correctly
cessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #)



### Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>amanda.carroll@labor.nc.gov</u>) to be uploaded to the intranet and the specific Unit.

Unit: District 1	Location of Inspection: Asheville Office
Inspection Team:	Date of Inspection: April 30, 2021
1. Kristie Hall	Unit Manager: Kay Knezevich
2	Additional Comments:
2.	No Issues.
3.	

## **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapters used or two prong extension cord
dditional Comments, notations, and abatement information (i	ncluding date):

Emergency Exit lighting is NOT working correctly Space heaters meet testing laboratories criteria (Identify)	Exit doors in working condition Block Exit doors
Space heaters meet testing laboratories criteria (Identify)	Plack Evit doors
	BIOCK EXIL GOOLS
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Kiddie Fire Extinguishers (#RD-379022 and #RD-379023)



### **Unit and Field Office Inspection Form**

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>amanda.carroll@labor.nc.gov</u>) to be uploaded to the intranet and the specific Unit.

Unit: Compliance - West	Location of Inspection: Charlotte
Inspection Team:	Date of Inspection: April 16, 2021
1. Griselle Negron	Unit Manager: Paul Sullivan
	Additional Comments:
2.	

# **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
ditional Comments, notations, and abatement information (i	ncluding date):

Space heaters meet testing laboratories criteria (Identify) Identify)   Flammable/Combustibles stored correctly Identify)	Exit doors in working condition Block Exit doors Chemicals stored correctly
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire outing lichard increated (identify by Carial #)
	Fire extinguishers inspected (identify by Serial #)



### Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Unit: OSH Compliance East	Location of Inspection: Lake Boone Trail – 1 <sup>st</sup> , 2 <sup>nd</sup> , 3 <sup>rd</sup> Floors; Parking Decks
Inspection Team:	Date of Inspection: April 29, 2021
1. Deborah Samad	Unit Manager: Dawn Eason
	Additional Comments:
2.	**See below re: Light fixtures in West Stairwell.
3.	

# **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
dditional Comments, notations, and abatement information (i	ncluding date):

	Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
X	Emergency Exit lighting is working correctly	Exit doors in working condition
	Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
	Flammable/Combustibles stored correctly	Chemicals stored correctly
	Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Inspected by landlord's agent, 4/19/21: KL-719206; BX-749520; BA-820835; (4/20/21): SX-011828; RX-347124. Inspected by D.S. (4/29/21): SL-128343. On parking decks: E79751508; E79818288.

Additional Comments, notations, and abatement information (including date): All of the light fixtures in the West Stairwell, up to and including the one on the landing between the 3<sup>rd</sup> and 4<sup>th</sup> floors: **FAILED** when tested: they did not illuminate when the test switch was pressed.



### Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Location of Inspection: Winston-Salem Pinnacle Building
Date of Inspection: 4/9/2021
Unit Manager: Ben Harris
Additional Comments:

# **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
ditional Comments, notations, and abatement information (ir	ncluding date): All ok : 4/9/2021

Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Ten fire     extinguishers inspected (SA-772292, YP-234285, YE-208191, SL     102203, ZD-926241, X-530590, MR-669188, MR-669014, AB-     847629, MR-669961)   All ok-4/9/2021

lighting in both stairwells had no power-hazardous to employees-during next power outage, CSHO will verify if this still an issue.