# NCDOL S

### **Employee Safety and Health Program**

#### **Unit and Field Office Inspection Form**

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<a href="mailto:amanda.carroll@labor.nc.gov">amanda.carroll@labor.nc.gov</a>) to be uploaded to the intranet and the specific Unit.

Unit: District 1	Location of Inspection: Asheville Office
Inspection Team:	Date of Inspection: April 2019
1. Kristie Hall	Unit Manager: Kay Knezevich
2. Leighton Dowdle	Additional Comments:
	No Issues.
3.	

### **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
litional Comments, notations, and abatement information (i	including date):

tems stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is NOT working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Kiddie Fire Extinguishers (#RD-379022 and #RD-379023)

Additional Comments, notations, and abatement information (including date): The AED (HeartStart FR2+ defibrillator) was checked, to include: located in designated location, no damage or missing parts, battery was charged, a spare battery was present, and AED pads are current.

# NCDOL S

# **Employee Safety and Health Program**

#### **Unit and Field Office Inspection Form**

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (Amanda.Carroll@labor.nc.gov). To be uploaded to the intranet and the specific Unit.

Unit: OSH Compliance East	Location of Inspection: Lake Boone Trail, 3 <sup>rd</sup> , 2 <sup>nd</sup> , 1 <sup>st</sup> floors and Parking Deck
Inspection Team:	Date of Inspection: April 16, 2019
1. Deborah Samad	Unit Manager: Bruce Miles
2.	Additional Comments:
	No deficiencies or hazards apparent.
3.	

## **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
itional Comments, notations, and abatement information (i	including date):

Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) KL-71920 BA-820835; SL-128343; ZC-871744; RX-347124; BX-749520.