

## **Employee Safety and Health Program**

#### **Unit and Field Office Inspection Form**

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (Amanda.Carroll@labor.nc.gov). To be uploaded to the intranet and the specific Unit.

Unit: CKARLOTTE	Location of Inspection: CLARLOTTE	
Inspection Team:	Date of Inspection: 17 (7 12019	
1. TEDHENDEIX	Unit Manager: PAUL SUCCIVAL)	
2.	Additional Comments:	
3.		

# **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
Additional Comments, notations, and abatement information (	(including date):
SWITCH COULD MISSING IN JANI	

ms stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
ergency Exit lighting is working correctly	Exit doors in working condition
ce heaters meet testing laboratories criteria (Identify)	Block Exit doors
mmable/Combustibles stored correctly	Chemicals stored correctly
cessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #)

# NCDOL S

# **Employee Safety and Health Program**

#### **Unit and Field Office Inspection Form**

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Unit: Winston-Salem Compliance West Field Office	Location of Inspection: Winston-Salem Pinnacle Building
Inspection Team: Jim Dempsey	Date of Inspection: 12/20/2019
1.	Unit Manager: Ben Harris
	Additional Comments:
Z.	
3.	

## **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
itional Comments, notations, and abatement information (i	including date): All ok-12/20/2019

Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Ten fire extinguishers inspected (SA-772292, YP-234285, YE-208191, S 102203, ZD-926241, X-530590, MR-669188, MR-669014, AB-847629, MR-669961 All ok-12/20/2019

# NCDOL S

#### **Employee Safety and Health Program**

#### **Unit and Field Office Inspection Form**

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (amanda.carroll@labor.nc.gov) to be uploaded to the intranet and the specific Unit.

Unit: District 1	Location of Inspection: Asheville Office
Inspection Team:	Date of Inspection: December 2019
1. Kristie Hall	Unit Manager: Kay Knezevich
	Additional Comments:
Z.	No Issues.
3.	

### **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapters used or two prong extension cord
itional Comments, notations, and abatement information (i	including date):

tems stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is NOT working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Kiddie Fire Extinguishers (#RD-379022 and #RD-379023)

Additional Comments, notations, and abatement information (including date): The AED (HeartStart FR2+ defibrillator) was checked, to include: located in designated location, no damage or missing parts, battery was charged, a spare battery was present, and AED pads are current.

# NCDOL S

#### **Employee Safety and Health Program**

#### **Unit and Field Office Inspection Form**

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (Amanda.Carroll@labor.nc.gov). To be uploaded to the intranet and the specific Unit.

Unit: OSH Compliance East	Location of Inspection: Lake Boone Trail, 3 <sup>rd</sup> , 2 <sup>nd</sup> , 1 <sup>st</sup> floors and Parking Decks
Inspection Team:	Date of Inspection: December 11, 2019
1. Deborah Samad	Unit Manager: Dawn Eason
	Additional Comments:
2.	
3.	

## **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Aissing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
itional Comments, notations, and abatement information (	including date):

ire Hazards and Egress: Check appropriate box when cor	ndition is identified and make notation
Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Inspected by landlord's agent, 12/2/19: KL-719206; BA-820835; BX-749520; ZC-871744; SL-128343. 12/6/19: RX-347520. 2 new fire extinguishers added by landlord, on parking decks: E-79751508 E-79818288: in locked boxes; OK per visual inspection.

Additional Comments, notations, and abatement information (including date): \*\* Stand Pipe, per label on 1st Floor, outside the door to the west stairwell, appears due for (5 Year) inspection, (last inspection 11/25/14).