NCDOL S

Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Unit: OSH Compliance East	Location of Inspection: Lake Boone Trail, 3 rd , 2 nd , 1 st floors and Parking Deck
Inspection Team:	Date of Inspection: September 30, 2019
1. Deborah Samad	Unit Manager: Dawn Eason
	Additional Comments:
2.	
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
xcessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
itional Comments, notations, and abatement information (i	ncluding date):

F	ire Hazards and Egress: Check appropriate box when con	diti	on is identified and make notation
	Items stored within 3 feet of a heater and/or heat source		Blocked fire extinguishers
	Emergency Exit lighting is working correctly	X	Exit doors in working condition - see below
	Space heaters meet testing laboratories criteria (Identify)		Block Exit doors
	Flammable/Combustibles stored correctly		Chemicals stored correctly
	Excessively warm/overheated cords or equipment:		Fire extinguishers inspected (identify by Serial #) KL-719206; BA-820835; BX-749520; RX-347124; ZC-871744: inspected by landlord's agent 9/20/19. SL-128343: inspected by D. Samad 9/30/19.

Additional Comments, notations, and abatement information (including date): In the fire alarm panel room on the first floor: the door to the stairs down to the parking deck closes in an uncontrolled manner, and slams so hard, and so fast, it could cause injury if someone had their hand on the door frame.

NCDOL S

Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (amanda.carroll@labor.nc.gov) to be uploaded to the intranet and the specific Unit.

Unit: District 1	Location of Inspection: Asheville Office
Inspection Team:	Date of Inspection: September 27, 2019
1. Kristie Hall	Unit Manager: Kay Knezevich
2	Additional Comments:
Ζ.	No Issues.
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
xcessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapters used or two prong extension cord
itional Comments, notations, and abatement information (i	including date):

Fire Hazards and Egress: Check appropriate box when cor	ndition is identified and make notation
Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is NOT working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Kiddie Fire Extinguishers (#RD-379022 and #RD-379023)

Additional Comments, notations, and abatement information (including date): The AED (HeartStart FR2+ defibrillator) was checked, to include: located in designated location, no damage or missing parts, battery was charged, a spare battery was present, and AED pads are current.



Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (Amanda.Carroll@labor.nc.gov). To be uploaded to the intranet and the specific Unit.

Unit: Complisaco - W3T	Location of Inspection: CLARIDITE
Inspection Team:	Date of Inspection: 2019/09/23
1. EDITORAL	Unit Manager: Pausucius
2.	Additional Comments:
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
xcessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
itional Comments, notations, and abatement information (i	ncluding date):
NEXE	

ems stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #)
tional Comments, notations, and abatement information (inclu	reline details