

Γ

Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Unit: OSH Compliance East	Location of Inspection: Lake Boone Tr., 1 st , 2 nd , 3 rd floors and Parking Deck
Inspection Team:	Date of Inspection: 12/31/2018
1. Deborah Samad	Unit Manager: Bruce Miles
	Additional Comments:
2.	
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
ditional Comments, notations, and abatement information (i	including date):

	Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Χ	Emergency Exit lighting is working correctly	Exit doors in working condition
	Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
	Flammable/Combustibles stored correctly	Chemicals stored correctly
	Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #): <i>were</i> <i>inspected by landlord's agent 12/28/18.</i> KL-719206; MX-832020; YZ-947825; ZC-871744; 7Z-947814 YZ-947616.

Additional Comments, notations, and abatement information (including date): Emergency light fixture **FAIL**: West stairwell, #94, 1st floor, at door to fire panel room: did not illuminate when tested. Note: West stairwell: lens is broken on light fixture at/above door to 2nd floor.



Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Location of Inspection:
Date of Inspection: 2018 [12/19
Unit Manager: PAUC Success
Additional Comments:

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
ditional Comments, notations, and abatement information	(including date):
MI OULAN	
AL OKAY	

Fire Hazards and Egress: Check appropriate box when co	ndition is identified and make notation
Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is working correctly	Exit doors in working condition
 Space heaters meet testing laboratories criteria (Identify) 	C Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #)
Additional Comments, notations, and abatement information (incl ACCOKAY	uding date):



Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>amanda.carroll@labor.nc.gov</u>) to be uploaded to the intranet and the specific Unit.

Unit: District 1	Location of Inspection: Asheville Office
Inspection Team:	Date of Inspection: December 2018
1. Kristie Hall	Unit Manager: Kay Knezevich
	Additional Comments:
2. Leighton Dowdle	The emergency exit light on the left side of the office in
3.	the back by the men's restroom is not working.

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
ditional Comments, notations, and abatement information (including date):

	Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
X	Emergency Exit lighting is NOT working correctly	Exit doors in working condition
	Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
	Flammable/Combustibles stored correctly	Chemicals stored correctly
	Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Kiddie Fire Extinguishers (#RD-379022 and #RD-379023)
in	•	ding date): The AED (HeartStart FR2+ defibrillator) was checked, t s, battery was charged, a spare battery was present, and AED pads