NCDOL S

Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Unit: OSH Compliance East	Location of Inspection: Lake Boone Trail – 1 st , 2 nd , 3 rd Floors; Parking Decks
Inspection Team:	Date of Inspection: June 30, 2021
1. Deborah Samad	Unit Manager: TBA (BC Nicole Brown)
	Additional Comments:
2.	**See below re: Light fixtures in West Stairwell.
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
itional Comments, notations, and abatement information (including date):
tional Comments, notations, and abatement information (i	including date).

Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (by landlord's agent, 6/30/21) (identify by Serial #): BA 820835; KL-719206; RX-347124; BX-749520; SL-128343; and on 6/22/21: SX-011828.

NCDOL S

Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (amanda.carroll@labor.nc.gov) to be uploaded to the intranet and the specific Unit.

Unit: District 1	Location of Inspection: Asheville Office
Inspection Team:	Date of Inspection: June 28, 2021
1. Kristie Hall	Unit Manager: Kay Knezevich
2	Additional Comments:
2.	No Issues.
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
lissing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapters used or two prong extension cord
itional Comments, notations, and abatement information (i	ncluding date):

tems stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is NOT working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Kiddie Fire Extinguishers (#RD-379022 and #RD-379023)

Additional Comments, notations, and abatement information (including date): The AED (HeartStart FR2+ defibrillator) was checked, to include: located in designated location, no damage or missing parts, battery was charged, a spare battery was present, and AED pads are current.

Employee Safety and Health Program



Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (amanda.carroll@labor.nc.gov) to be uploaded to the intranet and the specific Unit.

Unit: Compliance - West	Location of Inspection: Charlotte
Inspection Team:	Date of Inspection: June 17, 2021
1. Griselle Negron	Unit Manager: Paul Sullivan
	Additional Comments:
2.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring		
Damaged cords (any type)	Exposed energized parts		
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)		
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover		
	Two prong adapter used or two prong extension cord		
dditional Comments, notations, and abatement information (including date):			

ms stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
nergency Exit lighting is working correctly	Exit doors in working condition
ace heaters meet testing laboratories criteria (Identify)	Block Exit doors
ammable/Combustibles stored correctly	Chemicals stored correctly
cessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #)

NCDOL S

Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (Amanda.Carroll@labor.nc.gov). To be uploaded to the intranet and the specific Unit.

Unit: Winston-Salem Compliance West Field Office	Location of Inspection: Winston-Salem Pinnacle Building
Inspection Team: James Dempsey	Date of Inspection: 6/11/2021
1.	Unit Manager: Ben Harris
2.	Additional Comments:
2.	
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
itional Comments, notations, and abatement information (i	including date): All ok : 6/11/2021

Fi	Fire Hazards and Egress: Check appropriate box when condition is identified and make notation		
	Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers	
	Emergency Exit lighting is working correctly	Exit doors in working condition	
	Space heaters meet testing laboratories criteria (Identify)	Block Exit doors	
	Flammable/Combustibles stored correctly	Chemicals stored correctly	
	Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Ten fire extinguishers inspected (SA-772292, YP-234285, YE-208191, SL-102203, ZD-926241, X-530590, MR-669188, MR-669014, AB-847629, MR-669961) All ok-6/11/2021	

Additional Comments, notations, and abatement information (including date): Defibrillation electrode pads (Phillips Adult / Child Multifunction Electrode Pads (2) Part # M3713A expires 2022-05-31, During recent power outage, it was noted that the emergency lighting in both stairwells had no power-hazardous to employees-during next power outage, CSHO will verify if this still an issue. Some lights in 2nd floor men's bathroom are out or not working normally. (6/11/21)