# NCDOL S

### **Employee Safety and Health Program**

#### **Unit and Field Office Inspection Form**

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Unit: Winston-Salem Compliance West Field Office	Location of Inspection: Winston-Salem Pinnacle Building
Inspection Team: James Dempsey	Date of Inspection: 03/04/2022
1.	Unit Manager: Ben Harris
2	Additional Comments:
2.	
3.	

### **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapters used or two prong extension cords
itional Comments, notations, and abatement information (i	including date): All ok : 03/04/2022

Fire Hazards and Egress: Check appropriate box when condition is identified and make notation		
Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers	
Emergency Exit lighting is working correctly	Exit doors in working condition	
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors	
Flammable/Combustibles stored correctly	Chemicals stored correctly	
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Ten fire extinguishers inspected (SA-772292, YP-234285, YE-208191, SL-102203, ZD-926241, X-530590, MR-669188, MR-669014, AB-847629, MR-669961) All ok: 03/04/2022	

Additional Comments, notations, and abatement information (including date): Defibrillation electrode pads (Phillips Adult / Child Multifunction Electrode Pads (2) Part # M3713A expires 2022-05-31, Defib battery replaced-12/21/21. During recent power outage, it was noted that the emergency lighting in both stairwells had no power-hazardous to employees-during next power outage, CSHO will verify if this still an issue.

# NCDOL S

## **Employee Safety and Health Program**

#### **Unit and Field Office Inspection Form**

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<a href="mailto:amanda.carroll@labor.nc.gov">amanda.carroll@labor.nc.gov</a>) to be uploaded to the intranet and the specific Unit.

Unit: District 1	Location of Inspection: Asheville Office
Inspection Team:	Date of Inspection: March 31, 2022
1. Kristie Hall	Unit Manager: Kay Knezevich
	Additional Comments:
Z.	Received the new Cardiac Science defibrillator (AED)
	March 1, 2022.

### **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
dissing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapters used or two prong extension cord
itional Comments, notations, and abatement information (i	ncluding date):

tems stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
mergency Exit lighting is NOT working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Kiddie Fire Extinguishers (#RD-379022 and #RD-379023)

Additional Comments, notations, and abatement information (including date): The AED (Cardiac Science) defibrillator was checked, and it was in its designated location, there was no damage or missing parts, the battery was charged, and the AED pads were current.

# NCDOL S

## **Employee Safety and Health Program**

#### **Unit and Field Office Inspection Form**

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Location of Inspection: Lake Boone Trail 3 <sup>rd</sup> , 2 <sup>nd</sup> , 1 <sup>st</sup> floors and parking decks.
Date of Inspection: March 24, 2022
Unit Manager:
Additional Comments:

## **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
itional Comments, notations, and abatement information (i	including date):

Fi	Fire Hazards and Egress: Check appropriate box when condition is identified and make notation		
	Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers	
X	Emergency Exit lighting is working correctly	Exit doors in working condition	
	Space heaters meet testing laboratories criteria (Identify)	Block Exit doors	
	Flammable/Combustibles stored correctly	Chemicals stored correctly	
	Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #): A 30378830; BA 820835; BX 749520; RX 347124; SX 011828; SL 128343.	
Additional Comments, notations, and abatement information (including date): <b>Emergency light fixture </b> failure: above door from lab			

Additional Comments, notations, and abatement information (including date): **Emergency light fixture** <u>failure</u>: above door from lab to elevator lobby.