

Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Unit: CARLOTTE OSH	Location of Inspection:
Inspection Team:	Date of Inspection: 2/24/2020
1. TEDLEADER	Unit Manager:
2.	Additional Comments:
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
ditional Comments, notations, and abatement information	(including date):

Fire Hazards and Egress: Check appropriate box when co	ndition is identified and make notation
Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Energency Exit lighting is working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Ere extinguishers inspected (identify by Serial #)
Additional Comments, notations, and abatement information (Inc.	luding date): CORNER OF HEALTH SIDE (OUCE
BEVERY STONES CUBICIE) C	YOES NOT WORK



Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>amanda.carroll@labor.nc.gov</u>) to be uploaded to the intranet and the specific Unit.

Unit: District 1	Location of Inspection: Asheville Office
Inspection Team:	Date of Inspection: March 2020
1. Kristie Hall	Unit Manager: Kay Knezevich
2	Additional Comments:
2.	No Issues.
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapters used or two prong extension cord
dditional Comments, notations, and abatement information (i	ncluding date):

Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting is NOT working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibles stored correctly	Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Kiddie Fire Extinguishers (#RD-379022 and #RD-379023)
	luding date): The AED (HeartStart FR2+ defibrillator) was checked, ts, battery was charged, a spare battery was present, and AED pads



Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Unit: Winston-Salem Compliance West Field Office	Location of Inspection: Winston-Salem Pinnacle Building
Inspection Team: James Dempsey	Date of Inspection: 03/24/2020
1.	Unit Manager: Ben Harris
2	Additional Comments:
2.	
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
litional Comments, notations, and abatement information (including date): All ok 03/24/2020

Items stored within 3 f	eet of a heater and/or heat source	Blocked fire extinguishers
Emergency Exit lighting	is working correctly	Exit doors in working condition
Space heaters meet tes	ting laboratories criteria (Identify)	Block Exit doors
Flammable/Combustibl	es stored correctly	Chemicals stored correctly
Excessively warm/over	heated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Ten fire extinguishers inspected (SA-772292, YP-234285, YE-208191, SL 102203, ZD-926241, X-530590, MR-669188, MR-669014, AB- 847629, MR-669961 All ok-03/24/2020