# NCDOL S

## **Employee Safety and Health Program**

#### **Unit and Field Office Inspection Form**

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Unit: OSH Compliance East	Location of Inspection: Lake Boone Trail – 1 <sup>st</sup> , 2 <sup>nd</sup> , 3 <sup>rd</sup> Floors; Parking
Inspection Team:	Date of Inspection: March 26, 2021
1. Deborah Samad	Unit Manager: Dawn Eason
2	Additional Comments:
Z.	**See below re: Light fixtures in West Stairwell.
3.	

### **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
itional Comments, notations, and abatement information (i	ncluding date):

	Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
(	Emergency Exit lighting is working correctly	Exit doors in working condition
	Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
	Flammable/Combustibles stored correctly	Chemicals stored correctly
	Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) KL-719206; RX-347124; BA-820835; BX-749520; SX-011828; SL-128343; (on Parking Decks: E79751508; E79818288.

Additional Comments, notations, and abatement information (including date): All of the light fixtures in the West Stairwell, up to and including the one on the landing between the 3<sup>rd</sup> and 4<sup>th</sup> floors: **FAILED** when tested: they did not illuminate when the test switch was pressed.

# NCDOL S

## **Employee Safety and Health Program**

#### **Unit and Field Office Inspection Form**

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (amanda.carroll@labor.nc.gov) to be uploaded to the intranet and the specific Unit.

Unit: District 1	Location of Inspection: Asheville Office
Inspection Team:	Date of Inspection: March 29, 2021
1. Kristie Hall	Unit Manager: Kay Knezevich
2	Additional Comments:
Z.	No Issues.
3.	

### **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
lissing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapters used or two prong extension cord
itional Comments, notations, and abatement information (i	including date):

tems stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
mergency Exit lighting is NOT working correctly	Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors
lammable/Combustibles stored correctly	Chemicals stored correctly
excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Kiddie Fire Extinguishers (#RD-379022 and #RD-379023)

Additional Comments, notations, and abatement information (including date): The AED (HeartStart FR2+ defibrillator) was checked, to include: located in designated location, no damage or missing parts, battery was charged, a spare battery was present, and AED pads are current.

# NCDOL S

### **Employee Safety and Health Program**

#### **Unit and Field Office Inspection Form**

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (<u>Amanda.Carroll@labor.nc.gov</u>). To be uploaded to the intranet and the specific Unit.

Unit: Winston-Salem Compliance West Field Office	Location of Inspection: Winston-Salem Pinnacle Building
Inspection Team: James Dempsey	Date of Inspection: 3/12/2021
1.	Unit Manager: Ben Harris
2	Additional Comments:
3.	

## **Inspection Information**

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
itional Comments, notations, and abatement information (	including date): All ok : 3/12/2021

ire Hazards and Egress: Check appropriate box when condition is identified and make notation		
Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers	
Emergency Exit lighting is working correctly	Exit doors in working condition	
Space heaters meet testing laboratories criteria (Identify)	Block Exit doors	
Flammable/Combustibles stored correctly	Chemicals stored correctly	
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Ten fire extinguishers inspected (SA-772292, YP-234285, YE-208191, SL-102203, ZD-926241, X-530590, MR-669188, MR-669014, AB-847629, MR-669961 All ok-except south stairway FE, tag not replaced: 3/12/2021	

Additional Comments, notations, and abatement information (including date): Defibrillation electrode pads (Phillips Adult / Child Multifunction Electrode Pads (2) Part # M3713A expires 2022-05-31, During recent power outage, it was noted that the emergency lighting in both stairwells had no power-hazardous to employees-during next power outage, CSHO will verify if this still an issue. South Stairway FE tag not replaced, likely not serviced as well.