

Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Dawain Faison (dawain.faison@labor.nc.gov). to be uploaded to the intranet and the specific Unit.

Unit: District 10	Location of Inspection: Wilmington Field Office
Inspection Team:	Date of Inspection: 19/20/2017
1. Julie Martin	Unit Manager: Lafayette Atkinson
2. Michael Humann	Additional Comments:
2. Michael Humann	No hazants observed.
3.	

Inspection Information

Cords in walkways	Ø ✓ Extension cords used as permanent wiring
Damaged cords (any type)	ok Exposed energized parts
Missing ground pin on electrical cord	pt Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Ok Outlet missing cover or broken cover
	のと Two prong adapter used or two prong extension cord

Items stored within 3 feet of a heater and/or heat source	Øc Blocked fire extinguishers
Emergency Exit lighting is working correctly	Ok Exit doors in working condition
Space heaters meet testing laboratories criteria (Identify)	^g χ Block Exit doors
Flammable/Combustibles stored correctly	ρχ Chemicals stored correctly
Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) KA-00306597; A-32918438; 3-281688
	V TB-722667
	VA32918433
Additional Comments, notations, and abatement information (inc	uding date): OK

First Aid Kit: Replaced band-aid boxes (2) in the office kit. Both boxes had been used (empty) but no injuries or issues had been reported.

MONTHLY OFFICE INSPECTION WINSTON-SALEM FIELD OFFICE

DATE OF	INSPECTION: 10/17	PERFORM	ED BY: _	Sam/Russ	
FIRE EXT	INGUISHERS:	2			
<u>V</u>	Front Lobby (#1)				
V	Hallway (#2)				
<u>/</u> /	South Stairwell (#3)			a d	
/	Sign Out board (#4)		FIRST A	AID KIT	
0	IH Lab (#5)		V	ОК	
0	South Exit Stairwell (#6)	·	-	Needs supplies	
	Main Fire Stairwell (#6)				
EMERGEN	ICY LIGHTS		DEFILBI	RILLATOR	
	South Exit Stairwell (#27)			Electrode Pads	
0	South Hallway (#29)			Battery OK	
<u>v</u>	North Walkway (#31)				
V	Supervisor's Hall (#33)				
EXIT SIGN	S		BATHRO	OOMS	
	Front Door		<u> </u>	Men's	
<u></u>	Front Stairwell (#48)		<u> </u>	Women's	
<u></u>	South Work Station (#30)				
	Back Door (#28)				
1	North Work Station (#32)				
V .	South Reception (#34)				
$\frac{V}{}$	Top of Main Stairs (#51)				
	In Front of Elevator (#50)				

NCDOL S

Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (Amanda.Carroll@labor.nc.gov). To be uploaded to the intranet and the specific Unit.

Unit: OSH Compliance East	Location of Inspection: Lake Boone Tr., 1st, 2nd, 3rd floors and Parking Deck
Inspection Team:	Date of Inspection: 10/31/2017
1. Deborah Samad	Unit Manager: Bruce Miles
	Additional Comments:
	Most of the emergency light fixtures and emergency lighting/Exit
	signs that failed last month (and for some months previously) have been restored to function by the landlord's maintenance team.

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
lissing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
tional Comments, notations, and abatement information (including date):

Fi	Fire Hazards and Egress: Check appropriate box when condition is identified and make notation		
	Items stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers	
X	Emergency Exit lighting is working correctly See below:	Exit doors in working condition	
	Space heaters meet testing laboratories criteria (Identify)	Block Exit doors	
	Flammable/Combustibles stored correctly	Chemicals stored correctly	
	Excessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) MX-832020; YZ-947825; YZ-947814; YZ-947616; KL-719206; ZC-871744.	
—		\ \ \ 	

Additional Comments, notations, and abatement information (including date): Emergency lighting/Exit signs which **FALL**:

2nd Floor.: Conference Rm. B, #45. West Stairwell: Landing between parking deck and 1st Floor, #95: (test button broken: unable to test); at door to 2nd Floor, #92. East Stairwell: Landing between 1st and 2nd Floors, #102 (test button broken: unable to test).

NCDOL S

Employee Safety and Health Program

Unit and Field Office Inspection Form

Provide copy of this completed form to the Bureau Chief, and the Employee Safety and Health Program via Amanda Carroll (amanda.carroll@labor.nc.gov) to be uploaded to the intranet and the specific Unit.

Unit: District 1	Location of Inspection: Asheville Office
Inspection Team:	Date of Inspection: October 30, 2017
1. Kristie Hall	Unit Manager: Kay Knezevich
2. Leighton Dowdle	Additional Comments:
	No hazards were found during the inspection.
3.	

Inspection Information

Cords in walkways	Extension cords used as permanent wiring
Damaged cords (any type)	Exposed energized parts
Missing ground pin on electrical cord	Daisy chain (power strip plugged into another power strip)
Excessively warm/overheated cords or equipment:	Outlet missing cover or broken cover
	Two prong adapter used or two prong extension cord
itional Comments, notations, and abatement information (i	ncluding date):

tems stored within 3 feet of a heater and/or heat source	Blocked fire extinguishers
mergency Exit lighting is working correctly	Exit doors in working condition
pace heaters meet testing laboratories criteria (Identify)	Block Exit doors
lammable/Combustibles stored correctly	Chemicals stored correctly
xcessively warm/overheated cords or equipment:	Fire extinguishers inspected (identify by Serial #) Kiddie Fire Extinguishers (#RD-379022 and #RD-379023)
ional Comments, notations, and abatement information (inclu	iding date):